This is a CONTROLLED DOCUMENT EG&G - ROCKY FLATS PLANT ENVIRONMENTAL MANAGEMENT This is a RED Stamp

ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL

Manual No.: Procedure No.:

5-21000-OPS-SW Table of Contents, Rev 10

Page:

Effective Date:

05/11/93

Organization:

Environmental Management

THIS IS ONE VOLUME OF A SIX VOLUME SET WHICH INCLUDES:

VOLUME I: FIELD OPERATIONS (FO)
VOLUME II: GROUNDWATER (GW)
VOLUME III: GEOTECHNICAL (GT)
VOLUME IV: SURFACE WATER (SW)
VOLUME V: ECOLOGY (EE)
VOLUME VI: AIR (AP)

TABLE OF CONTENTS
FOR VOLUME IV: SURFACE WATER

Procedure <u>No.</u>	Title	Rev. <u>No.</u>	Effective <u>Date</u>
SW.01	Surface Water Data Collection Activities	2	05/12/92
DCN 92.01	Assure Quality Control	2	07/21/92
SW.02	Field Measurement of Surface Water Field Parameters	2	05/12/92
DCN 92.01	Allow Change In Instrumentation	2	07/21/92
DCN 92.02	Reduction In Chlorine Testing Requirements	2	07/21/92
*DCN 93.01	Alkalinity Titration Delays	2	05/11/93
SW.03	Surface Water Sampling	2	05/12/92
SW.04	Discharge Measurement	2	05/12/92
SW.05	Base Laboratory Work		To Be Added
SW.06	Sediment Sampling	2	05/12/92
DCN 92.01	Reduction In Personal Protectional Level		
	Due to Local Knowledge	2	07/21/92
DCN 92.02	Clarification of Sampling	2	09/29/92
SW.07	Collection of Tap Water Samples	2	05/12/92

ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL Manual No.: Procedure No.: Page: Effective Date: 5-21000-OPS-SW Table of Contents, Rev 10 2 of 2 05/11/93

Organization:

Environmental Management

Proc. No.	Title	Rev. No.	Effective <u>Date</u>
SW.08 DCN 92.01	Pond Sampling Clarification of Sampling	2 2	05/12/92 10/05/92
SW.09	Industrial Effluent and Pond Discharge Sampling	2	05/12/92
SW.10 DCN 93.01	Event-Related Surface Water Sampling Table Replacement-Attachment 1	1 1	02/20/92 01/15/93
SW.11	Operation and Maintenance of Stream-Gaging and Sampling Stations	1	02/20/92
SW.12 DCN 92.01	Site Description Reduction in Unrequired Quality Check	2 2	05/12/92 07/21/92
SW.13	Bacteriological Water Sampling	2	05/12/92
SW.14	Automatic Sampling	T	o Be Added
SW.15	River and Ditch Sampling	2	05/12/92
SW.16	Sampling of Incidental Waters	2	05/12/92
SW.17 DCN 93.01	Pond and Reservoir Bottom Sediment Sampling Decontamination	0 0	09/25/92 01/15/93
SW.28	Field Locating Effluent Pathways and Drains	0	09/25/92
SW.29	Dye Testing Building Drains	0	09/29/92
SW.30	Field Locating Chemicals of Concern	0	09/25/92
SW.33	Dye Testing Foundation Footing Drains	0	09/29/92

1//

This is a ENVIRONMENTAL MANAGEMENT CONTROLLED DOCUMENT DOCUMENT CHANGE NOTICE (DCN)

EG&G - ROCKY FLATS PLANT FNYLRONMENTAL MANAGEMENT This is a RED Stamp

Page	1	of	1

Title				Date 5.11-93	DCN Number		
	Fie	eld Measurements	of Surface Water Field Parameters	April 29-1993 SURN	73.01 2011,2943 84Ri		
Expires _	5,	119 A SUE	4.2443 Procedure Revision Required Y	es 🗆 No			
Scope Lin	nitation:.	OU6					
Item Number	Page	Step or Paragraph	Changes (Use DCN CONTINUATION SHEET for additional space)				
1	12	5.6	Change the first paragraph of section 5.6 to read as follows. Alkalinity measurements will accompany pH measurements as described in Subsection 5.5 of this procedure where required. The alkalinity measurements can be done either in the field or in the base laboratory. The titration should be done within 24 hours after collection. Sampling for storm runoff commonly requires collection of water samples in bulk with containerization and preservation of inorganic constituents within several hours at the base laboratory in accordance with SOP FO.13: Containerization, Preserving, Handling, and Shipping of Soil and Water Samples. In these instances, it is desirable to perform the alkalinity titration in the base laboratory in order to simplify the complicated logistics of sampling in rain storms and to prevent contamination of the alkalinity sample with rain water or other materials such as mud. Titration with an appropriate acid reagent will be used to measure alkalinity. Alkalinity measurements at the RFP will be conducted with a HACH digital titrator of equivalent. Follow the general procedures described below and see equipment manufacturer's instructions for detailed equipment-specific titration procedures.				
			DOCUME PER R.E	ENT CLASSIFICATION I B. HOFFMAN, CLASSIF JUNE 11, 199	ICATION OFFICE		

1. Synoptic sampling of storm events for the Operable Unit Number 6 (OU6) Phase I RFI/RI requires manual sampling of storm runoff at 15 locations in OU6. This logistically complicated exercise requires collection of water samples in adverse weather conditions which slows down sampling crews and increases the chance of sample contamination. In order to expedite and simplify sample collection during storm events, alkalinity titrations and sample filtration must occur in the base laboratory instead of in the field. This SOP must be modified to allow delay of the alkalinity titrations until the sample is returned to the base laboratory several hours after collection.

Concurrence	Organization	Req.	Date	Сопситепсе	Organization	Req.	Date
Allomite	Į QAPM	х	5/10/93	Moni	User		4/28/93
11. Growsand	Fom	X	5-3-93	Mile C. Broke	EQS		4/29/93
, , , , ,							
			<u> </u>				
Approval of Responsible manager		Date	163	Is Posting required?	If Yes, by what d	ate OT	Date posted